



GDI HIGH-PRESSURE FUEL PUMP KITS

WHAT'S IN YOUR BOX?

StandardWhatsInYourBox.com

The All-in-One High-Pressure Fuel Pump Solution

Blue Streak® award-winning kits make it easier to perform a complete GDI high-pressure fuel pump service.

What's inside the Blue Streak® box...
precision manufacturing and
everything needed for a complete
repair. What's in your box?

Blue Streak® Kits are available for popular import and domestic applications, and include the components needed to optimize GDI fuel pressure:

- High-Pressure Fuel Pump
- Cam Follower
- Mounting Hardware
- Seals



Precision-manufactured kits include everything required for a complete service



New Product of the Year
Award Winner


100%
TESTED & VALIDATED

Lab tested and validated on
actual vehicles

Blue Streak® Solutions

Problem:

Fault codes P0087 (fuel pressure is too low) or P0088 (fuel pressure is too high) can be caused by a failed GDI high-pressure fuel pump OR a failed camshaft follower.



Blue Streak® Solution:

Installing a new high-pressure pump with a new cam follower helps ensure correct fuel pressure in the GDI system.



Blue Streak® delivers all-in-one kits



GDP114K
GM Cars and SUVs
(2019-16) VIO: 1.6M



Made to stand the test of time,
Blue Streak® by Standard® has always
been known for quality and durability.



STANDARDBLUESTREAK.COM



SMPCORP.COM

BS11770